



Grande Prairie
(780) 539-3594
(80) 532-8047 (Fax)

Dispatch
1-888-540-3594
www.reesndt.com

Bonnyville
(780) 573-7630
Email: ronvader@reesndt.com

INSPECTION DATE: 28-Jun-2007

CLIENT: Viper Rentals & Services Ltd.

ADDRESS: 10709 95 ST.

High Level AB T0H 1Z0

REES NDT PO NUMBER: R6197

CLIENT PO NUMBER:

REES NDT WO NUMBER: 110950

NACE/API INSPECTION CERTIFICATE


ITEM: Dual Sided Flange
MANUFACTURER: Hi Kalibre Equipment
SERIAL NUMBER: VRS 1511
MODEL: 3 1/8 5000 R35 x 2 1/16 5000 R24
RATED WORKING PRESSURE: 5000 psi
NACE MR0175 COMPLIANT: Yes
ANSI/API 6A COMPLIANT: Yes

Rees NDT Inspection Services Limited performed a VISUAL, WET FLUORESCENT MAGNETIC PARTICLE AND HARDNESS TESTING inspection on the above mentioned DUAL SIDED FLANGE. All observations have been recorded and are disclosed in the Rees NDT Inspection Report for Work Order #110950 with the understanding that this certification is limited to the unit's structural competence and does not constitute or imply a capacity rating. The capacity noted above reflects the original equipment manufacturer's maximum capacity rating and may be reduced by operating conditions, regulatory requirements and the use of auxillary equipment that has a lower capacity rating.


The undersigned Engineer reviewed all inspection reports upon completion of any required repairs. Based on this review of final inspection results, it is our opinion, that the DUAL SIDED FLANGE may be returned to service and operated within the original manufacturer's specifications.

This certification covers the above mentioned unit for a period of 3 YEARS AS PER CAODC RECOMMENDED PRACTICE 6.0/7.0, with inspections by a qualified person as per CAODC RP 6.0 /7.0 or until the unit is damaged by handling, transportation, operation or should the blowout preventer (BOP) be subjected to an uncontrolled flow, pressure in excess of the manufacturer's rating, sour fluid exposure (where the equipment is not rated for sour service) or significant well control operations.

Reviewed By:



Nov 16/07



in service Apr. 18, 2013